


KERRISON PUNCH SERVICING








ARE YOU EXPERIENCING?

- Dull cutting edge causing incomplete cut
- Damaged springs
- Missing screws
- Burred t-track causing friction while in use



OUR SOLUTION

- We sharpen the cutting edge providing a clean total bone excision
- Replace or reset all springs and to tolerances
- Replace any absent screws
- Deburr / remachine and lubricate t-track

ORDER NOW